

Inspection Photos
Location Name: Razor #26J-2633L
API: 05-123-37495



Photo from prior inspection for comparison



Photo 1: Tanks are labeled

Inspection Photos
Location Name: Razor #26J-2633L
API: 05-123-37495



Photo 2: Damaged tanks at battery.



Photo 3: Wellhead sign is for prior operator