

Bunker 5,6 Tank Battery
COGCC Location ID 307044
COGCC Site Inspection Photographs
July 6, 2017



Sign at crude oil AST



Crude oil AST.



Crude oil AST loadout.



Leaking crude oil AST valve north side of tank.



Produced water tank and spill area.



Valve on produced water AST.



Produced water AST lacks contents, capacity and operator information.



Impacted material stockpiled on location.



Graded farm/lease road looking north.



Graded farm/lease road looking south.