



Photo 1: View of riser at 37.53339, -108.62765, at entrance to access road.



Photo 2: View of riser at 37.53328, -108.62963, across county road entrance to project area. Lockout/tagout not observed.



Photo 3: View of revegetation on the well pad from the northern edge facing southward. Vegetation on the well pad appears to be more sparse than surrounding wheat crop.



Photo 4: View from the beginning of the access road facing southward toward the well pad. Vegetation in project area is more sparse than surrounding vegetation.