

Inspection Photos

7/11/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 323738

Inspection Doc. Number: 682502383

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323738



Photo 1: Photo taken from the well location, facing west. Photo shows all equipment have been removed, and location has been returned to cropland. A follow-up inspection will need to be conducted when crop is establishing to evaluate compliance with 1000 series reclamation standards.



Photo 2: Photo taken from the battery location, facing east. Photo shows facilities and equipment have all been removed.