

Inspection Photos

7/11/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 323695

Inspection Doc. Number: 682502389

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323695



Photo 1: Photo taken from the south end of the battery location, facing north. Photo shows battery location has not been adequately reclaimed. Vegetation seen here predominantly undesirable weedy plant species such as kochia, russian thistle and bindweed. Reference area perennial crop alfalfa.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323695



Photo 2: Photo taken from the battery location. Inspector attempted to dig multiple soil pits to test for compaction. Photo shows inspector was unable to penetrate more than ½ an inch throughout battery location. Compaction alleviation has not been sufficiently performed.



Photo 3: Photo taken from the adjacent reference area. Photo shows inspector had little resistance penetrating the topsoil in the reference area.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323695



Photo 4: Photo taken from the north end of the battery location, facing south. Photo shows area where access road traveled to the well. Crop along the disturbance appears stunted when compared to that of the reference area.



Photo 5: Photo taken from the well location, facing south. Crop along the disturbance appears stunted when compared to that of the reference area.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323695



Photo 6: Photo of disturbance quadrat #1



Photo 7: Photo of disturbance quadrat #1

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323695



Photo 8: Photo of disturbance quadrat #2



Photo 9: Photo of disturbance quadrat #2

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323695



Photo 10: Photo of reference quadrat #1



Photo 11: Photo of reference quadrat #1

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323695



Photo 12: Photo of reference quadrat #2



Photo 13: Photo of reference quadrat #2