

Inspection Photos
Location Name: BMC B Pad
Facility ID: 447695



Photo 1. Sound monitoring equipment 7/6/17



Photo 2. Sound monitoring equipment 7/6/17

Inspection Photos
Location Name: BMC B Pad
Facility ID: 447695



Photo 3. COGCC sound survey taken approximately 629 feet from Drilling location.