



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the western portion of the project area from the northwestern corner facing southward.



Photo 3: View of the southern portion of the project area from the southeastern corner facing westward.



Photo 4: View of sign that is knocked down.



Photo 5: View of approximately 500 Russian knapweed (*Acroptilon repens*) within the northwestern portion of the interim reclamation area.



Photo 6: Closeup view of Russian knapweed within the project area.



Photo 7: View of closed portion of road that was reclaimed in western portion of the project area.