

- Express Federal 1 05-083-06570



**Photo 1: 03/10/2017 Downed fencing photo from inspection document number 685302370.**

- Express Federal 1 05-083-06570



**Photo 2: 07/05/2017 Downed fencing photo from inspection document number 685303456.**

- Express Federal 1 05-083-06570



**Photo 3: 03/17/2017 Lube oil tank with no spill prevention photo from inspection document number 685302370.**

- Express Federal 1 05-083-06570



**Photo 4: 07/05/2017 Lube oil tank with no spill prevention photo from inspection document number 685303456.**

- Express Federal 1 05-083-06570



**Photo 5: 03/10/2017 Stained soil at wellhead photo from inspection document number 685302370.**

- Express Federal 1 05-083-06570



**Photo 6: 07/05/2017 Stained soil at wellhead photo from inspection document number 685303456.**

- Express Federal 1 05-083-06570



**Photo 7: 03/10/2017 Unmarked dead man photo from inspection document number 685302370.**

- Express Federal 1 05-083-06570



**Photo 8: 07/05/2017 Unmarked dead man photo from inspection document number 685303456.**

- Express Federal 1 05-083-06570



**Photo 9: 03/10/2017 Weeds around separator photo from inspection document number 685302370.**

- Express Federal 1 05-083-06570



**Photo 10: 07/05/2017 Weeds around separator photo from inspection document number 685303456.**

- Express Federal 1 05-083-06570



**Photo 11: 03/10/2017 Weeds in containment photo from inspection document number 685302370.**

- Express Federal 1 05-083-06570



**Photo 12: 07/05/2017 Weeds in containment photo from inspection document number 685303456.**