

Inspection Photos

7/12/2017

Operator: PDC ENERGY INC - 69175

Location ID: 407785

Inspection Doc. Number: 682502399

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 407785



Photo 1: Photo taken from the well location, facing south. Photo shows crop growth at the well location. Photo shows growth over the well location is stunted when compared to the adjacent reference area. This is likely due to compaction concerns. Inspector measured the height of multiple plants, average crop height within the disturbance areas was ~3.5 feet. Yellow line distinguishes well location vs. reference. 6 foot measuring stick for reference.

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 407785



Photo 2: Photo taken from the adjacent reference area. Photo shows crop growth over the reference. Inspector measured the height of multiple plants, average crop height within the disturbance areas was ~5.5 feet. Crop height on the disturbed is ~60% to that of the reference. 6 foot measuring stick for reference.