

# Inspection Photos

7/12/2017

Operator: FOUNTAINHEAD RESOURCES LTD -  
30658

Location ID: 322701

Inspection Doc. Number: 682502402

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: FOUNTAINHEAD RESOURCES LTD -  
30658  
Location ID: 322701



**Photo 1:** Photo taken from the southeast end of the location, facing northwest. Photo shows vegetation has not been returned to crop, or stabilized with total perennial, non-invasive uniform plant cover. Vegetation over location predominantly undesirable weedy plant species such as kochia, Russian Thistle and Canada horseweed, as well as Colorado State listed noxious weeds such as Musk thistle and bind weed.



**Photo 2:** Photo taken from the southeast end of the location, facing northeast. Photo shows vegetation has not been returned to crop, or stabilized with total perennial, non-invasive uniform plant cover. Vegetation over location predominantly undesirable weedy plant species such as kochia, Russian thistle and Canada horseweed, as well as Colorado State listed noxious weeds such as Musk thistle and bind weed.

Inspection Photos  
Operator: FOUNTAINHEAD RESOURCES LTD - 30658  
Location ID: 322701



**Photo 3:** Photo taken from the well location. Photo shows Musk thistle. This is a Colorado stated listed noxious weed and needs to be managed.