

Inspection Photos

7/12/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 328534

Inspection Doc. Number: 682502407

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 328534



Photo 1: Photo taken from the well location, facing east. Photo shows well has been plugged and removed. If compaction alleviation has not yet been performed, well will require cross ripping as well as revegetating to reflect the adjacent reference area.



Photo 2: Photo taken from the well location, facing north. Photo shows access road has yet to be reclaimed. Access road appears to require compaction alleviation, re-contouring, re-grading and re-vegetation. Reclamation rule 1004.a requires all such reclamation work be completed within twelve (12) months on non-crop land after plugging a well.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 328534



Photo 3: Photo taken from the north of the well location, facing west. Photo shows meter shed that has not been removed. Reclamation rule 1004.a requires that all equipment be removed within three months of plugging the associated facility.

Inspection Photos

Operator: NOBLE ENERGY INC - 100322

Location ID: 328534



Photo 4: Photo taken from the north end of the battery location, facing south west. Photo shows equipment at the battery facility have been removed. Battery location waiting additional reclamation activities; location appears to still require road base removal, compactions alleviation, re-contouring, re-grading and re-vegetation. Reclamation rule 1004.a requires all such reclamation work be completed within twelve (12) months on non-crop land after plugging a well.



Photo 5: Photo taken from the north end of the battery location, facing south west. Photo shows equipment at the battery facility have been removed. Battery location waiting additional reclamation activities; location appears to still require road base removal, compactions alleviation, re-contouring, re-grading and re-vegetation. Reclamation rule 1004.a requires all such reclamation work be completed within twelve (12) months on non-crop land after plugging a well.