

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/29/2017

Submitted Date:

07/12/2017

Document Number:

666803334**FIELD INSPECTION FORM**

Loc ID 334620 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287372	WELL	PR	09/01/2007	GW	045-12992	LAST DANCE 34-15 (P34NE)	PR
287373	WELL	PR	09/04/2007	GW	045-12991	LAST DANCE 34-15C (P34NE)	PR
287374	WELL	SI	01/01/2017	GW	045-12990	LAST DANCE 34-16 (P34NE)	SI
287375	WELL	PR	09/08/2007	GW	045-12989	LAST DANCE 34-16C (P34NE)	PR
287376	WELL	PR	05/05/2008	GW	045-12988	LAST DANCE 34-10 (P34NE)	PR
287377	WELL	PR	05/21/2008	GW	045-12987	LAST DANCE 34-9C (P34NE)	PR
287378	WELL	PR	05/02/2008	GW	045-12986	LAST DANCE 34-9 (P34NE)	PR
287379	WELL	PR	05/02/2008	GW	045-12985	LAST DANCE 34-10C (P34NE)	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		39.478307,-107.646998	
Comment:	Hooked up to bradenhead					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal					
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLs	STEEL AST		39.477934,-107.647338
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
<u>Venting:</u>					
Yes/No	YES				
Comment:	Bradenhead valve open				
Corrective Action:					Date:
<u>Flaring:</u>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities						
Facility ID:	287372	Type:	WELL	API Number: 045-12992	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	287373	Type:	WELL	API Number: 045-12991	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	287374	Type:	WELL	API Number: 045-12990	Status: SI	Insp. Status: SI
<b>Idle Well</b>						
Purpose:	<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:	
Comment:	Last posted production numbers Dec. 2016					
Corrective Action:						Date:
Facility ID:	287375	Type:	WELL	API Number: 045-12989	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	287376	Type:	WELL	API Number: 045-12988	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	287377	Type:	WELL	API Number: 045-12987	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	287378	Type:	WELL	API Number: 045-12986	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	287379	Type:	WELL	API Number: 045-12985	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Plunger lift					
Corrective Action:						Date:

Producing Well			
Comment:	Plunger lift		
Corrective Action:		Date:	

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Culverts	Pass			
		Gravel	Pass			
Berms	Pass					
		Ditches	Pass			
Ditches	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT