



**photo 1:** Facing north at the former tank battery site approximately 300' east of the well.



**photo 2:** There are pipe risers that remain at the tank battery site. Lat/Long:40.03149,-104.91935



**photo 3:** A second pipe riser was found at Lat/Long:40.03161,104.91930.



**photo 4:** There are List B noxious weeds (Diffuse knapweed) growing at the tank battery site.



**photo 5:** Facing southwest at the tank battery site. The desirable vegetation has not re-established.



**photo 6:** Facing southeast at the tank battery site. The desirable vegetation has not re-established.



**photo 7:** Facing west at the well site. The surrounding past vegetation has not re-established.



**photo 8:** Facing south toward the surrounding pasture.