

Inspection Photos  
Location Name: JSR 4-1  
API: 05-081-07070



**Photo 1. Overview of location taken at entrance facing northeast.**



**Photo 2. Only sign on location contains previous operator information.**

Inspection Photos  
Location Name: JSR 4-1  
API: 05-081-07070



**Photo 3. Risers at wellhead. Noxious weeds at wellhead. No sign at wellhead.**



**Photo 4. Meter run and risers not locked out tagged out.**