

Inspection Photos
Location Name: McCallum Unit 186
API: 05-057-06451



Photo 1. Overview of location facing west.



Photo 2. Stained soil at wellhead.