

Inspection Photos
Location Name: Sooner #21-16-9
API: 05-123-18968



Photo from prior inspection for comparison



Photo 1: Stained soil at wellhead, no bradenhead at surface