

Inspection Photos

7/14/2017

Operator: PDC ENERGY INC - 69175

Location ID: 332234

Inspection Doc. Number: 682502429

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 332234



Photo 1: Photo taken from the east end of the battery location, facing west. Photo shows all facilities except meter shed has been removed. Location appears to have been cross-ripped. 1004.a reclamation rules require removal of all debris, abandoned gathering line risers, and flowline risers, and equipment within three months of plugging (12/09/2016) the associated facility. Meter shed needs to be removed and location reseeded .



Photo 2: Photo of meter shed remaining at battery location. 1004.a reclamation rules require removal of all debris, abandoned gathering line risers, and flowline risers, and equipment within three months of plugging (12/09/2016) the associated facility. Meter shed needs to be removed and location reseeded .

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 332234



Photo 3: Photo shows sign found inside meter shed identifying PDC wells associated with this battery facility.

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 332234



Photo 4: Photo taken from the well location. Photo shows subsidence occurring at well. Photo also shows that well does not appear to have been reseeded and area remains bare with no sign of germination or growth from the spring growing season.



Photo 5: Photo taken from the well location. Photo shows subsidence occurring at well. Photo also shows that well does not appear to have been reseeded and area remains bare with no sign of germination or growth from the spring growing season.