

Inspection Photos

7/14/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 326836

Inspection Doc. Number: 682502431

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 326836



Photo 1: Photo taken from the well location, facing north. Photo shows crop vegetation over the reclamation area.



Photo 2: Photo taken from the well location, facing east. Photo shows crop vegetation over the reclamation area.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 326836



Photo 3: Photo taken from the well location, facing south. Photo shows crop vegetation over the reclamation area.



Photo 2: Photo taken from the well location, facing west. Photo shows crop vegetation over the reclamation area.