

- Simms 1A 05-067-06344



Photo 1: Wellhead sign.

- Simms 1A 05-067-06344



Photo 2: Produced water tank with no visible NFPA label.

- Simms 1A 05-067-06344



Photo 3: Produced water tank with signage/labeling on top of tank.

- Simms 1A 05-067-06344



Photo 4: Canadian Thistle on location perimeter.

- Simms 1A 05-067-06344



Photo 5: Production related debris.

- Simms 1A 05-067-06344



Photo 6: Pipe with vent inside separator fencing.