

- Morrison Federal 2 05-067-08949



Photo 1: Wellhead sign.

- Morrison Federal 2 05-067-08949



Photo 2: Weeds and grass inside production equipment fencing.

- Morrison Federal 2 05-067-08949



Photo 3: Produced water tank with labels not visible from outside containment.

- Morrison Federal 2 05-067-08949



Photo 4: Labels on top of tank.

- Morrison Federal 2 05-067-08949



Photo 5: Concrete and tree cuttings dumped on SE side of fill slope.

- Morrison Federal 2 05-067-08949



Photo 6: Close up of concrete, tree cuttings, and carcass.

- Morrison Federal 2 05-067-08949



Photo 7: Erosion gully on NW corner of location.

- Morrison Federal 2 05-067-08949



Photo 8: Erosion gully close up.