


GROUNDWATER SAMPLE ID
SAMPLE DATE
B: BENZENE CONCENTRATION
RESULTS IN MICROGRAMS PER LITER
BOLD INDICATES RESULT EXCEEDS STANDARD



LEGEND

- RELEASE LOCATION
- AIR SPARGING (AS) WELL
- SOIL VAPOR EXTRACTION (SVE) WELL
- MONITORING WELL
- DESTROYED MONITORING WELL
- ABANDONED MONITORING WELL
- REMOVED FROM MONITORING PROGRAM
- GROUNDWATER SAMPLE
- METER HOUSE
- SURVEYED GROUNDWATER FLOW DIRECTION

- FENCE
- EXCAVATION EXTENT
- BERM
- CARBON SLURRY INJECTION AREAS (2014)




FIGURE 2
REMEDIATION SITE MAP
FRITZLER UPRR 31-31
NWNE SEC 31-T4N-R66W
WELD COUNTY, COLORADO
KERR-MCGEE OIL & GAS ONSHORE LP

