

Inspection Photos

7/17/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 323368

Inspection Doc. Number: 682502438

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323368



Photo 1: Photo taken from the well location, facing north. Photo shows crop vegetation over the reclamation area.



Photo 2: Photo taken from the well location, facing east. Photo shows crop vegetation over the reclamation area.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323368



Photo 3: Photo taken from the well location, facing south. Photo shows crop vegetation over the reclamation area.



Photo 2: Photo taken from the well location, facing west. Photo shows crop vegetation over the reclamation area.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323368



Photo 5: Photo taken from the access road. Photo shows deep ruts remain along access road indicated road had not been re-contoured or re-graded in accordance to COGCC 1000 series reclamation standards. Hat for reference

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323368



Photo 6: Photo taken from the access road. Photo shows rut in areas a foot deep (indicated by yellow line) or greater remain along access road. This indicates road has not been re-contoured or re-graded in accordance to COGCC 1000 series reclamation standards.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 323368



Photo 7: Photo taken from the access road, facing south. Photo shows ruts remain evident along access road (yellow arrows). It appears road had not been re-contoured or re-graded in accordance to COGCC 1000 series reclamation standards.



Photo 8: Photo taken from the access road, facing north. Photo shows ruts remain evident along access road (yellow arrows). It appears road had not been re-contoured or re-graded in accordance to COGCC 1000 series reclamation standards.