

Inspection Photos

Location Number: 330153



Photo 1 Battery from west, tires and gravel pile



Photo 2 Weeds within berm from west

Inspection Photos



Photo 3 Compromised berm from west



Photo 4 Wellhead from south

Inspection Photos



Photo 5 Closeup of wellhead signage



Photo 6 Rutting on access road from north

Inspection Photos



Photo 7 Weeds on and adjacent to access road from north



Photo 8 Gate requires maintenance note blocking under end of gate from north