

Inspection Photos
Location Name: Walker 12-4
API: 05-081-07080



Photo 1. Overview of location taken at entrance facing northwest.

Inspection Photos
Location Name: Walker 12-4
API: 05-081-07080



Photo 2. Unused 2" steel riser on left, unused 3" steel riser on right.



Photo 3. Unused 2" steel riser at wellhead.