

# Inspection Photos

## Location Number: 450025



**Photo 1 Signage, track pad at entrance from southeast**



**Photo 2 Ditch and hydro mulch at entrance from east**

# Inspection Photos



Photo 3 Fill and ditch on east side, photo from the south




Photo 4 Drilling Permit posted

# Inspection Photos



**Photo 5 Septic and potable water with secondary containment from north**



**Photo 6 Sediment retention and hydro mulch on southwest corner of location from north**

## Inspection Photos



**Photo 7 Chemical storage and secondary containment on north side of location from south**



**Photo 8 Cement cleanout apparatus.**