

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/17/2017

Submitted Date:

07/17/2017

Document Number:

679902771**FIELD INSPECTION FORM**

Loc ID 314216 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10227Name of Operator: CHOLLA PETROLEUM INCAddress: 6688 N CENTRAL EXPRESSWAY 1610City: DALLAS State: TX Zip: 75206**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Cahill, Terry	(214) 692-7052	tcahill@chollapetr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278882	WELL	PR	12/04/2007	GW	099-06885	MAGIWA UNIT 1-23	PR

General Comment:

Location**Lease Road:**

Type	Access		
comment:	Gravel road through pasture		
Corrective Action:		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Lease sign mounted to fence at solar panels		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on water tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Wire panels around HGS		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Wire panels around solar panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Wire panels around water tank		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	278882	Type:	WELL	API Number:	099-06885	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Access on west side of location is eroding. Install BMP to prevent further erosion

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT