

# Inspection Photos

7/19/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 408094

Inspection Doc. Number: 682502474

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 408094



**Photo 1:** Photo taken from the well location, facing southwest. Photo shows the Dickens F-32 tank battery has been constructed at the well location.




**Photo 2:** Photo taken from the Dickens F-32 tank battery.

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 408094



**Photo 3:** Photo taken from the former battery location. Photo shows riser remaining at location. COGCC rule 1004.a requires operator to remove all debris, abandoned gathering line risers, and flowline risers, and equipment within three months of plugging the associated facility. All work should have been conducted by 7/1/2008.



**Photo 4:** 2002 Aerial imagery showing the riser's location at the former battery, and the well location.