

Inspection Photos

7/19/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 332748

Inspection Doc. Number: 682502476

Weld County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 332748



Photo 1: Photo taken from the well location, facing west. Photo shows the well has been Pad and all equipment removed. Vegetation appears to be actively mowed.



Photo 2: Photo taken from the battery location. Photo shows sign at tank states "Stewart 1, 2".

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 332748



Photo 3: Photo taken from the battery location. Photo shows four (4) risers that appear to be abandoned.



Photo 4: Photo taken from the battery location. Photo shows four (4) risers that appear to be abandoned.