



Photo 1: View of the project area from the northeastern corner facing center.



Photo 2: View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is progressing, largely with grasses such as western wheatgrass (*Pascopyrum smithii*), smooth brome (*Bromus inermis*), and intermediate wheatgrass (*Thinopyron intermedium*).



Photo 3: View of the southern portion of the project area from the southeastern corner facing westward.



Photo 4: View of diversion in the eastern portion of the project area that is starting to erode.



Photo 5: View of reference area at 37.269471, -107.619866. Species observed include the following:

- Ponderosa pine (*Pinus ponderosa*)
- Gambel's oak (*Quercus gambelii*)
- Squirreltail (*Elymus elymoides*)
- Redroot buckwheat (*Eriogonum racemosum*)
- Muttongrass (*Poa fendleriana*)
- Fringed sage (*Artemisia rigida*)
- Mugwort (*Artemisia ludoviciana*)
- Oregon grape (*Mahonia repens*)
- Yarrow (*Achillea millefolium*)
- Antelope bitterbrush (*Purshia tridentata*)
- Mules ears (*Wyethia arizonica*)
- Locoweed (*Astragalus* sp.)
- Cushion pussytoes (*Antennaria dimorpha*)