

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/18/2017

Submitted Date:

07/21/2017

Document Number:

682600334**FIELD INSPECTION FORM**
 Loc ID 449153 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 61650Name of Operator: MURFIN DRILLING COMPANY INCAddress: 250 N WATER ST STE 300City: WICHITA State: KS Zip: 67202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Kerstetter, Sarah	316-858-8668	skerstetter@murfininc.com	Designated Agent
Gunzelman, Shauna	316-267-3241	sgunzelman@murfininc.com	Designated Agent
Housey, Melissa		melissa.housey@state.co.us	
Melland, Tom	316-858-8695	tmelland@murfininc.com	Production Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449154	WELL	DG	07/11/2017		073-06718	Milk Money #3	EI

General Comment:

Operator has received approval via Form 4 docnum 401337444 to change disposal of drilling fluid from Commercial Disposal to Land Application.

This is an environmental inspection to document status of Land Application of water based bentonitic drilling fluids. Any corrective actions from previous inspections that have not been addressed are still applicable.

Operator has constructed a reserve pit for storage of drill cuttings and fluids (see attached photos). At the time of inspection the drilling pits and land application were compliant with with COGCC regulations and the approved Form 4. Land application site is cropland.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 449154 Type: WELL API Number: 073-06718 Status: DG Insp. Status: EI**COGCC Comments**

Comment	User	Date
Operator has equipment on site to incorporate drilling fluid after land application (see attached photos). Drilling fluid must be incorporated within 10 days of land application.	kosolaj	07/21/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600335	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203260