



**Photo 1: View of the project area from the northeastern corner facing center.**



**Photo 2: View of the northern portion of the project area from the northeastern corner facing westward.**



**Photo 3: View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is progressing, largely with grasses such as western wheatgrass (*Pascopyrum smithii*) and smooth brome (*Bromus inermis*).**



**Photo 4: View of southern portion of the project area from the southeastern corner facing westward. Stormwater controls are in place.**