



Photo 1: View of the project area from the northeastern corner facing center.



Photo 2: View of the northern portion of the project area from the northeastern corner facing westward. Revegetation on the northern cut-slope is sparse.



Photo 3: View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is progressing, largely with grasses such as western wheatgrass (*Pascopyrum smithii*) and smooth brome (*Bromus inermis*).



Photo 4: View of the southern portion of the project area from the southeastern corner facing westward.



Photo 5: View of diversion in the eastern portion of the project area.