

July 20, 2017, COGCC Environmental Field Inspection of ARCH OIL AND GAS (Arch) Urie #2 Location ID: 312772.



Location sign.



Tank battery bermed.



Tank battery bermed.



Stained soil around well head.



Stained soil around well head.



Chemical containers not in secondary containment.