

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/24/2017

Submitted Date:

07/24/2017

Document Number:

679902795**FIELD INSPECTION FORM**

Loc ID 314181 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 83130Name of Operator: STRACHAN EXPLORATION INCAddress: 383 INVERNESS PKWY, STE 360City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Strachan, Steve	(303) 785-7006	sms@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
227805	WELL	PR	08/02/2002	GW	099-06131	STATE 3-8	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by wellhead. Update to current operator		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease sign mounted to meter shed		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tank. NFPA label will need to be replaced		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds around tank battery and meter shed need maintained		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Pipe fence around meter shed		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Wire fence around tank and metal shed		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Railroad ties around wellhead		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Vertical Separator	# 1			
Comment:	Vertical gas separator in metal shed north of production tank			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:	Meter run 2070' SSE of wellhead			
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	STEEL AST		38.151680,-102.480010	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	210bbls				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	227805	Type:	WELL	API Number:	099-06131	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Meter run for (STATE 3-8) 2070' SSE of wellhead @ 38.15193/-102.47991								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Compaction	Pass			

Comment: Location is grassed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT