

- Sanchez 2 05-067-05345



Photo 1: Wellhead sign.

- Sanchez 2 05-067-05345



Photo 2: 3" riser beside tank with no plug and stained soil around it.

- Sanchez 2 05-067-05345



Photo 3: Leaking production tank valve.

- Sanchez 2 05-067-05345



Photo 4: 3" riser at production tank.

- Sanchez 2 05-067-05345



Photo 5: Impacted soil at wellhead and loose pipe and fittings.

- Sanchez 2 05-067-05345



Photo 6: Risers at wellhead.

- Sanchez 2 05-067-05345



Photo 7: Open ended line.

- Sanchez 2 05-067-05345



Photo 8: Risers and lines at gas meter run.

- Sanchez 2 05-067-05345



Photo 9: Open ended line heading E from location.

- Sanchez 2 05-067-05345



Photo 10: Unmarked deadman.