

Inspection Photos  
Location Grant Properties #3  
API:05-001-07649



Sign at battery



Stained soil at drain line on tank

Inspection Photos  
Location Grant Properties #3  
API:05-001-07649



Stained soil inside berms at tank



Wellhead sign and stained soil

**Inspection Photos**  
**Location Grant Properties #3**  
**API:05-001-07649**



**Unused equipment**



**Stained soil from leaking gear box**

**Inspection Photos  
Location Grant Properties #3  
API:05-001-07649**



**Stained soil at motor mounts**



**Unused equipment**

**Inspection Photos  
Location Grant Properties #3  
API:05-001-07649**



**Unused equipment**



**Stained soil inside doghouse, trash**