

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/20/2017

Submitted Date:

07/20/2017

Document Number:

688400006

**FIELD INSPECTION FORM**

Loc ID 427917 Inspector Name: Gomez, Jason On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10110  
Name of Operator: GREAT WESTERN OPERATING COMPANY LLC  
Address: 1801 BROADWAY #500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427723	WELL	DG	07/12/2017	LO	123-35099	Raindance FC 23-369HN	DG
427727	WELL	DG	07/12/2017	LO	123-35100	Raindance FC 23-369HC	DG
451091	WELL	DG	07/11/2017		123-44982	Raindance FD 20-362HN	DG
451093	WELL	DG	07/06/2017		123-44983	Raindance FD 20-282HN	DG
451094	WELL	DG	07/09/2017		123-44984	Raindance FD 20-322HN	DG
451097	WELL	DG	07/10/2017		123-44987	Raindance FD 20-362HNX	DG
451098	WELL	DG	07/10/2017		123-44988	Raindance FD 20-359HC	DG
451099	WELL	DG	07/08/2017		123-44989	Raindance FD 20-319HN	DG
451101	WELL	DG	07/08/2017		123-44990	Raindance FD 20-319HNX	DG
451102	WELL	DG	07/07/2017		123-44991	Raindance FD 20-282HC	DG
451103	WELL	DG	07/06/2017		123-44992	Raindance FD 20-242HN	DG
451168	WELL	DG	07/14/2017		123-45007	Raindance FC 26-369HC	DG

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Ancillary equipment	#		corrective date
Comment: APPROX 32' SOUND WALLS AROUND LOCATION FOR SOUND MITIGATION			
Corrective Action: <input type="text"/>			Date: <input type="text"/>

**Venting:**

Yes/No	NO		
Comment: <input type="text"/>			
Corrective Action: <input type="text"/>			Date: <input type="text"/>

**Flaring:**

Type	Field Flare		
Comment: NOT IN USE AT TIME OF INSPECTION			
Corrective Action: <input type="text"/>			Date: <input type="text"/>

**Inspected Facilities**

Facility ID: 427723 Type: WELL API Number: 123-35099 Status: DG Insp. Status: DG

Facility ID: 427727 Type: WELL API Number: 123-35100 Status: DG Insp. Status: DG

Facility ID: 451091 Type: WELL API Number: 123-44982 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: PRECISION 460 Pusher/Rig Manager: MARVIN  
 Permit Posted: Yes Access Sign: Yes

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: \_\_\_\_\_ Safety Plan: YES

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: YES Disposal Location: WASTE MANAGEMENT

**Comment:** 1 OF 6 SURFACE HOLES COMPLETED ALL LIGHTS POINTED DOWN AND TOWARD THE GROUND

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 451093 Type: WELL API Number: 123-44983 Status: DG Insp. Status: DG

Facility ID: 451094 Type: WELL API Number: 123-44984 Status: DG Insp. Status: DG

Facility ID: 451097 Type: WELL API Number: 123-44987 Status: DG Insp. Status: DG

Facility ID: 451098 Type: WELL API Number: 123-44988 Status: DG Insp. Status: DG

Facility ID: 451099 Type: WELL API Number: 123-44989 Status: DG Insp. Status: DG

Facility ID: 451101 Type: WELL API Number: 123-44990 Status: DG Insp. Status: DG

Facility ID: 451102 Type: WELL API Number: 123-44991 Status: DG Insp. Status: DG

Facility ID: 451103 Type: WELL API Number: 123-44992 Status: DG Insp. Status: DG

Facility ID: 451168 Type: WELL API Number: 123-45007 Status: DG Insp. Status: DG

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass	Material Handling And Spill Prevention	Pass	
Mulching	Pass	Waddles	Pass			
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
Gravel	Pass	Gravel	Pass	Vehicle Tracking	Pass	

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401349659	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203057">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203057</a>