

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/20/2017

Submitted Date:

07/20/2017

Document Number:

688400012

FIELD INSPECTION FORM

Loc ID 305447 Inspector Name: Gomez, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		Cogcc.inspections@crestonepr.com	
		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277773	WELL	PR	09/30/2009	GW	123-22988	WOOLLEY 12-7	WO
434333	WELL	PR	01/01/2017	LO	123-38104	Woolley Sosa 2A-7H-E168	WO
434334	WELL	PR	01/01/2017	LO	123-38105	Woolley Becky 2F-7H-E168	WO
434335	WELL	PR	01/01/2017	LO	123-38106	Woolley Sosa 2D-7H-E168	WO
434336	WELL	PR	01/01/2017	LO	123-38107	Woolley Becky 2D-7H-E168	WO
434337	WELL	PR	01/01/2017	LO	123-38108	Woolley Sosa 2B-7H-E168	WO
434338	WELL	PR	01/01/2017	LO	123-38109	Woolley Becky 2B-7H-E168	WO
434339	WELL	PR	01/01/2017	LO	123-38110	Woolley Sosa 2E-7H-E168	WO
434340	WELL	PR	01/01/2017	LO	123-38111	Woolley Becky 2A-7H-E168	WO
434341	WELL	PR	01/01/2017	LO	123-38112	Woolley Becky 2E-7H-E168	WO
434342	WELL	PR	01/01/2017	LO	123-38113	Woolley Sosa 2F-7H-E168	WO
434343	WELL	PR	01/01/2017	LO	123-38114	Woolley Becky 2H-7H-E168	WO
436731	WELL	PR	01/01/2017	LO	123-39241	Woolley Becky 2C-7H-E168	WO
436733	WELL	PR	01/01/2017	LO	123-39242	Woolley Becky 2G-7H-E168	WO
436738	WELL	PR	01/01/2017	LO	123-39245	Woolley Sosa 2C-7H-E168	WO
436739	WELL	PR	01/01/2017	LO	123-39246	Woolley Sosa 2G-7H-E168	WO

General Comment:

Inspected Facilities				
Facility ID: <u>277773</u>	Type: <u>WELL</u>	API Number: <u>123-22988</u>	Status: <u>PR</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434333</u>	Type: <u>WELL</u>	API Number: <u>123-38104</u>	Status: <u>PR</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434334</u>	Type: <u>WELL</u>	API Number: <u>123-38105</u>	Status: <u>PR</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434335</u>	Type: <u>WELL</u>	API Number: <u>123-38106</u>	Status: <u>PR</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434336</u>	Type: <u>WELL</u>	API Number: <u>123-38107</u>	Status: <u>PR</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434337</u>	Type: <u>WELL</u>	API Number: <u>123-38108</u>	Status: <u>PR</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434338</u>	Type: <u>WELL</u>	API Number: <u>123-38109</u>	Status: <u>PR</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434339</u>	Type: <u>WELL</u>	API Number: <u>123-38110</u>	Status: <u>PR</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434340</u>	Type: <u>WELL</u>	API Number: <u>123-38111</u>	Status: <u>PR</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434341</u>	Type: <u>WELL</u>	API Number: <u>123-38112</u>	Status: <u>PR</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434342</u>	Type: <u>WELL</u>	API Number: <u>123-38113</u>	Status: <u>PR</u>	Insp. Status: <u>WO</u>
Facility ID: <u>434343</u>	Type: <u>WELL</u>	API Number: <u>123-38114</u>	Status: <u>PR</u>	Insp. Status: <u>WO</u>
Facility ID: <u>436731</u>	Type: <u>WELL</u>	API Number: <u>123-39241</u>	Status: <u>PR</u>	Insp. Status: <u>WO</u>
Facility ID: <u>436733</u>	Type: <u>WELL</u>	API Number: <u>123-39242</u>	Status: <u>PR</u>	Insp. Status: <u>WO</u>
Facility ID: <u>436738</u>	Type: <u>WELL</u>	API Number: <u>123-39245</u>	Status: <u>PR</u>	Insp. Status: <u>WO</u>
Facility ID: <u>436739</u>	Type: <u>WELL</u>	API Number: <u>123-39246</u>	Status: <u>PR</u>	Insp. Status: <u>WO</u>

Complaint

Comment: **Complaint Received July 20, 2017**

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 7-19-2017 Time 2158 Hrs

Contacted by: Jason Gomez+

Date: 7- 20-2017 Time 1100 Hrs

Well Number#: Location #: 336382

Inspection Document #: 688400012

Nature of complaint: Noise

Field Inspector Actions:

On 7-20-2017, I was contacted by complaint specialist Megan Adamczyk in reference to several complaints received by the COGCC about noise occurring in the Erie are of CR 10.5 and WCR 3.

On 7-20-2017, I performed a complete site inspection of the Woolley Becky Sosa location. Upon inspection of the location I observed a flowback operation being conducted by Crestone. I reviewed location records, which did not show any abnormal flow back activity at the time of the complaints. I also reviewed Environmental Noise Control Inc. continuous sound study information which also did not show any exceedance of COGCC rules at the times of the complaints.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

No violations of COGCC rules were observed at the time of the inspection.

Corrective Action:

Date:

Completion

Operation: Flowback

Date Flowback: 07/20/2017

Contractor: BASIC

Comment: DRILL OUT OPERATION ON LOCATION

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401349663	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4203061