

Inspection Photos  
Location Name: Peter McCue 30-3  
API: 05-081-07829



Photo 1. Overview of location from entrance facing south.



Photo 2. No berm around tank.

Inspection Photos  
Location Name: Peter McCue 30-3  
API: 05-081-07829



**Photo 3. Cuttings and drilling equipment stored on location.**



**Photo 4. Cuttings stored on location.**