

Inspection Photos  
Location Name: George Gerhardt 2  
API: 05-123-08124



Photo from prior inspection for comparison



Photo 1: Stained soil removed