

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/27/2017

Submitted Date:

07/27/2017

Document Number:

689400054

FIELD INSPECTION FORM

Loc ID 312679 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Elsener, Garrett		garrett@caerusoilandgas.com	
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Encana,		cogcc.inspections@encana.com	All Inspections
Janicek, Jake		JJanicek@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264988	WELL	TA	01/01/2017	GW	077-08775	ORCHARD 16-12 (L16)	TA

General Comment:

Form 10 Change of Operator Doc#401353916 in process

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	2	<50 BBLs	STEEL AST		,

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate	
-----------	----------	--

Other (Content) Diesel	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 264988 Type: WELL API Number: 077-08775 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Gravel	Pass					
Compaction	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT