

Inspection Photos  
Location Nessua 4  
API:05-123-08810



Sign at wellhead



Stained soil at wellhead





**Inspection Photos**  
**Location Grant Properties #3**  
**API:05-001-07649**



**Stained soil inside berms at tank**



**Wellhead sign and stained soil**

**Inspection Photos**  
**Location Grant Properties #3**  
**API:05-001-07649**



**Unused equipment**



**Stained soil from leaking gear box**



**Inspection Photos**  
**Location Grant Properties #3**  
**API:05-001-07649**



**Stained soil at motor mounts**



**Unused equipment**

**Inspection Photos**  
**Location Grant Properties #3**  
**API:05-001-07649**



**Unused equipment**



**Stained soil inside doghouse, trash**