

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/27/2017

Submitted Date:

07/27/2017

Document Number:

689500063**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 316576      GRANAHAH, KYLE      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10384Name of Operator: GENESIS GAS & OIL COLORADO LLCAddress: 1660 LINCOLN ST STE 2100City: DENVER      State: CO      Zip: 80246**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Jensen, David	(816) 222-7500	djensen@genesisco.com	Exec. VP
Behner, Robert	816-222-7500	bbehner@genesisco.com	VP

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286509	WELL	SI	05/14/2013	GW	103-10890	FLETCHER GULCH 4-44	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Present/complete		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-361-3007

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	286509	Type:	WELL	API Number:	103-10890	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: EQUIPMENT ONSITE									
Comment: <input type="text" value="SI - no leaks/venting - current MIT - doc # 1726895"/>									
Corrective Action: <input type="text"/> Date: <input type="text"/>									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Compaction	Pass					

Comment: No sediment flow evident

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT