

June 13, 2017 COGCC Environmental Field Inspection of POC-I LLC (POC) Isle Dome Location ID: 312756, Pit Facility ID: 116589.



Location sign.



West side of tank battery looking north.



East side of tank battery looking north.



Location east of tank battery.



Chemical container next to monitoring well.



Dedicated bailer in monitoring well.





3" PVC disconnected from Tank #1(southern most tank) and is connected at the top of the tank.



Fluid being discharged to trough via garden hose from Tank #5. App 15 gpm.





Concrete vault/pit.



Trash storage (absorbent booms).



Pit with compromised net.





Pit with compromised net.



Pit with hydrocarbon sheen.



Pit Facility ID 116589.



Pit Facility ID 116589.



Pit Facility ID 116589 with sediment flow into pit.



Diversion ditch to pit.





Monitoring well near NW corner of Pit ID 116589.



Trash (water bottle) NW corner of Pit ID 116589.



Open access to Pit. NW Corner.





NW corner of Pit ID 116589.



Discharge to unnamed stream flowing into Spring

Gulch.



Discharge to unnamed stream flowing into Spring

Gulch.



Boom down stream from discharge.



Low flow area down stream from boom.