

- Day-V-Ranch 34-1/2 35 1 05-067-07468



Photo 1: Wellhead sign.

- Day-V-Ranch 34-1/2 35 1 05-067-07468



Photo 2: Weeds on berms and base of containment.

- Day-V-Ranch 34-1/2 35 1 05-067-07468



**Photo 3: Tank labeling and weeds.**

- Day-V-Ranch 34-1/2 35 1 05-067-07468



**Photo 4: Waddles with backside full of sediment.**

- Day-V-Ranch 34-1/2 35 1 05-067-07468



**Photo 5: Waddles with backside full of sediment.**

- Day-V-Ranch 34-1/2 35 1 05-067-07468



**Photo 6: Erosion channels and rilling in NE corner of cut slope carrying sediment onto location.**



- Day-V-Ranch 34-1/2 35 1 05-067-07468



**Photo 7: Erosion around fence post concrete.**

- Day-V-Ranch 34-1/2 35 1 05-067-07468



**Photo 8: Waddle and sediment flow in SW corner.**

- Day-V-Ranch 34-1/2 35 1 05-067-07468



Photo 9: Waddle in SW corner.

- Day-V-Ranch 34-1/2 35 1 05-067-07468



Photo 10: Waddle and sediment flow at location entrance.