

# Inspection Photos

7/24/2017

Operator: EXTRACTION OIL & GAS INC

Location ID: 329578

Inspection Doc. Number: 675103753

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: EXTRACTION OIL & GAS INC  
Location ID: 329578



**Photo 1:** Photo taken from the well location, facing north. Photo shows fence around well.



**Photo 2:** Photo taken from the well location. Photo shows well still remaining above ground and exposed

Inspection Photos  
Operator: EXTRACTION OIL & GAS INC  
Location ID: 329578



Photo 3: Photo taken west of the well. Photo shows vent pipe from line. If line from well to former battery has been abandoned, this should be removed.




Photo 4: Current aerial imagery. Photo shows location of well, riser (vent) and former battery location.