

Inspection Photos

7/27/2017

Operator: PETRO-CANADA RESOURCES (USA) INC -
72085

Location ID: 376781

Inspection Doc. Number: 675103765

Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the west end of the well pad. Photo shows location has not been re-contoured/re-graded per CA's



Photo 2: Photo taken from the well. Photo shows well location has not achieved uniform, desirable perennial vegetative cover. Unable to find evidence that additional reclamation activities have been conducted.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311664



Photo 3: Photo taken from the west end of the location, facing west. Photo shows access road leading to the well has not been re-contoured.



Photo 4: Photo taken from the west end of the location, facing west. Photo shows access road leading to the well has not been re-contoured. Yellow line indicates elevation of the adjacent reference area, hat in photo for reference to show depth of road.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311664



Photo 5: Photo taken from the fenced remediation area. Photo shows unvegetated areas. Unable to find evidence that additional reclamation or remediation activities have been conducted.



Photo 6: Photo taken from the fenced remediation area. Photo shows unvegetated areas. Unable to find evidence that additional reclamation or remediation activities have been conducted.



Photo 5: Photo taken from access road, facing south. Photo shows access road has not been re-contoured or re-graded.