

Inspection Photos

7/27/2017

Operator: PETRO-CANADA RESOURCES (USA) INC -
72085

Location ID: 375675

Inspection Doc. Number: 675103767

Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311664



Photo 1: Photo taken from the well location, facing south. Photo shows area of the well remains unvegetated. Unable to find evidence to suggest additional reclamation activities have been conducted.



Photo 2: Photo taken from the well location, facing east. Photo shows area of the well remains unvegetated. Unable to find evidence to suggest additional reclamation activities have been conducted.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311664



Photo 3: Photo taken from down slope of the well location, facing north. Photo shows areas of erosion and that not BMPs have been installed to mitigate degradation.



Photo 4: Photo taken from the fenced remediation area, facing east. Photo shows areas of the remediation that remain unvegetated, or predominantly undesirable weedy plant species such as kochia and Russian thistle. Unable to find evidence to suggest additional remediation or reclamation activities have been conducted.