

Inspection Photos

7/27/2017

Operator: WALSH* FRANK H - 94100

Location ID: 375209

Inspection Doc. Number: 675103773

Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the well location, facing north. Photo shows areas of the well location that remain bare and exposed soil.

Inspection Photos
Operator: WALSH* FRANK H - 94100
Location ID: 375209



Photo 2: Photo taken from the northeast end of the pit location, facing south. Photo shows pit remains open.



Photo 3: Photo taken from the northeast end of the pit location, facing west. Photo shows pit remains open.