

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/28/2017

Submitted Date:

07/28/2017

Document Number:

689700097**FIELD INSPECTION FORM**

Loc ID 334627 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name          | Phone        | Email                              | Comment |
|-----------------------|--------------|------------------------------------|---------|
| Inspection, Terra TEP | 970-263-2760 | COGCCInspectionReports@terraep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 210921      | WELL | PR     | 02/13/2014  | GW         | 045-06679 | GV 81-5       | PR          |
| 274730      | WELL | PR     | 02/19/2005  | GW         | 045-13382 | PA 411-5      | PR          |
| 274939      | WELL | PR     | 02/25/2005  | GW         | 045-13443 | PA 511-5      | PR          |
| 287291      | WELL | PR     | 10/05/2006  | GW         | 045-12951 | PA 312-5      | PR          |
| 287292      | WELL | PR     | 10/05/2006  | GW         | 045-12950 | PA 12-5       | PR          |
| 287293      | WELL | PR     | 10/05/2006  | GW         | 045-12949 | PA 412-5      | PR          |
| 287294      | WELL | PR     | 10/05/2006  | GW         | 045-12948 | PA 512-5      | PR          |
| 287804      | WELL | PR     | 07/23/2007  | GW         | 045-13041 | PA 522-5      | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | SEPARATOR    |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | WELLHEAD     |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

|                                   |      |       |                 |
|-----------------------------------|------|-------|-----------------|
| <b>Equipment:</b>                 |      |       | corrective date |
| Type: Plunger Lift                | # 8  |       |                 |
| Comment:                          |      |       |                 |
| Corrective Action:                |      | Date: |                 |
| Type: Bird Protectors             | # 8  |       |                 |
| Comment:                          |      |       |                 |
| Corrective Action:                |      | Date: |                 |
| Type: Horizontal Heated Separator | # 14 |       |                 |

|                    |  |       |
|--------------------|--|-------|
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Tanks and Berms:**

|                    |   |          |           |         |        |
|--------------------|---|----------|-----------|---------|--------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
| PRODUCED WATER     | 1 | 200 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

|                    |   |          |           |         |        |
|--------------------|---|----------|-----------|---------|--------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
| CONDENSATE         | 1 | 300 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |       |  |
|--------------------|-------|--|
| Yes/No             | NO    |  |
| Comment:           |       |  |
| Corrective Action: | Date: |  |

**Flaring:**

|                    |       |  |
|--------------------|-------|--|
| Type               |       |  |
| Comment:           |       |  |
| Corrective Action: | Date: |  |

| Inspected Facilities  |                |       |      |             |           |         |    |               |    |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 210921         | Type: | WELL | API Number: | 045-06679 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 274730         | Type: | WELL | API Number: | 045-13382 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | 334627         |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 274939         | Type: | WELL | API Number: | 045-13443 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | 334627         |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 287291         | Type: | WELL | API Number: | 045-12951 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | 334627         |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 287292         | Type: | WELL | API Number: | 045-12950 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | 334627         |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 287293         | Type: | WELL | API Number: | 045-12949 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | 334627         |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 287294         | Type: | WELL | API Number: | 045-12948 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | 334627         |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |
| Facility ID:          | 287804         | Type: | WELL | API Number: | 045-13041 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | 334627         |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             | Date:     |         |    |               |    |

|  |
|--|
|  |
|--|

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            |                         |                       |               |                          |         |
|                  |                 | Ditches                 | Pass                  |               |                          |         |
| Gravel           | Pass            |                         |                       |               |                          |         |
|                  |                 | Compaction              | Pass                  |               |                          |         |
| Seeding          | Pass            |                         |                       |               |                          |         |
|                  |                 | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT